

भारत सरकार GOVERNMENT OF INDIA  
रेल मंत्रालय MINISTRY OF RAILWAYS  
(रेलवे बोर्ड) (RAILWAY BOARD)

सं.2007/Tele/MW/1/WOP

नई दिल्ली, दिनांक:21/12/2012

**TELECOM CIRCULAR NO. 15/2012**

The General Managers/ All Indian Railways,  
ALL PUs, CORE/ALD,  
MD/RailTel,  
DGs/RDSO & Railway Staff College, IG/RPF,  
CAOs/COFMOW,DCW,IRPMU & New PUs at Chappra & Raebareli,  
Directors/IRISET,IRICEN,IRIEEN,IRIMEE,IRITM,  
Chairman, All Indian Railway Recruitment Boards.

**Sub: Precautions for avoiding fire hazards and responsibility of SSE/Tele.**

\*\*\*

A number of cases of damage to telecom equipment/installation because of fire has been reported to Board that has lead to huge losses for Railways. It is therefore essential that Railways ensure suitable fire fighting arrangement at all Telecom activity centers especially at OFC repeaters, MW stations, Telecom control, test rooms, Railnet server location, ISS control centre and Telecom stores.

It should be the responsibility of the SSE/Incharge to ensure that the fire-fighting appliances at various locations under his charge are kept in a condition fit for immediate use. SSE/Tele shall also see that the staff under him are conversant with the method of their operation and also arrange trials periodically to test these appliances for fitness and the knowledge of the staff handling the fire-fighting appliances and the method of their operation. The appliances shall be recharged immediately after they have been used.

Railways may ensure the above.



(राकेश रंजन)

निदेशक/दूरसंचार

दूरभाष: 011-23388504, 030-44613

फैक्स: 011-23304690, 030-44690

ई मेल:dtele@rb.railnet.gov.in