

भारत सरकार (GOVERNMENT OF INDIA)
रेल मंत्रालय (MINISTRY OF RAILWAYS)
रेलवे बोर्ड (RAILWAY BOARD)

No.2020/Tele/9(1)/1(3326798)

Rail Bhawan, New Delhi-110001

Dated: 21.02.2022

The Director General
R.D.S.O., Manak Nagar,
Lucknow – 226 011

Sub.: Deregulation/decontrol of select Telecom items

Ref: (i) RDSO's letter no. STT/Controlled-Decontrolled Items/901 dated 04.02.2022 & 20.12.2021.
(ii) RDSO's letter No. no. RDSO/2018/QS/RB/Policy/1759 dated 24.01.2022 & 22.01.22.

* * * * *

Vide letter under reference(i) dated 04.02.22, recommendations of the 39th Telecom Standards Committee (TCSC) meeting held on 29.01.2022 have been received. The same have been examined by Board and Board's approval as in Annexure-A, is hereby communicated.

2. RDSO will issue test formats for inspection for all the items which have been decontrolled. Further, whenever RDSO specifications are revised, based on Zonal Railways' requirements/technical advancements, test formats will also be revised by RDSO.

3. Recommendation pertaining to informal items viz. (i) Video Surveillance System & (ii) VHF sets are under examination and Board's decision on the same will be communicated in due course.

Signed by Dharmendra

(धर्मन्द्र सिंह)

Date: 22-02-2022 15:58:37

निदेशक/दूरसंचार

दूरभाष: 011-47843013, 030-44613

ई.मेल: dtele@rb.railnet.gov.in

Copy to:

1. ED/Signal/Railway Board for suitable amendments in Signalling, if required, in view of Decontrolling of PIJF Cable.
2. General Managers(S&T), All Indian Railways

Annexure-A

Sr. No.	Item	UVAM-ID	Railway Board's approval
1.	Emergency Control Room Equipment	3100039	Item decontrolled for vendor development and RDSO inspection. However, RDSO specification to continue and RITES/Third party inspection is mandated.
2.	Quad cable for S&T installation.	3100047	Being directly related to safety of train operation, RDSO specification, vendor development and inspection to continue.
3. & 4.	24 Fibre armoured optic fibre cable and 24/48 fibre armoured optic fibre cable.	3100049 3100187	RDSO specification, vendor development and inspection to continue. To increase vendor base, TEC approved vendors to be considered with RDSO inspection.
5.	Desk type 2 wire, 12 Way DTMF telephone	3100124	Item decontrolled for vendor development and RDSO inspection. However, RDSO specification to continue and RITES/Third party inspection is mandated.
6.	Six Pin Emergency Plug and Socket	3100134	Item decontrolled. RDSO specification to continue. RITES/Third party inspection is mandated.
7.	Primary Digital Multiplexing Equipment	3100137	RDSO specification, vendor development and inspection to continue.
8.	Polythene insulated Polythene sheathed Jelly Filled Telephone Cable with poly-AL Moisture Barrier.	3100310	Item decontrolled. TEC specifications to be used. RITES/Third party inspection is mandated.
9.	Power Supply for Telecom (i) Power Supply Unit (PSU) for Telecom Installation at Way Side Stations in 25 KV Electrified Area (ii) SMPS based Power Plant for IRs Telecom Equipment	3100314	Item decontrolled. RDSO specification to continue. RDSO specification, vendor development and inspection to continue
10.	Telecom jointing kits (i) For joining of underground quad cable (ii) For jointing of underground PIJF cable for derivation.	3100332	(i) RDSO specification, vendor development and inspection to continue. (ii) Item decontrolled. RDSO specification to continue. RITES/Third party inspection is mandated.
11	VF Transformers (i) 2T/3T Transformer for derivation (ii) VF & Signalling Transformer for derivation	3100343	Item decontrolled. RDSO specification to continue. RITES/Third party inspection is mandated.
12.	Auto Dialling system for Emergency socket	3100346	Item decontrolled. RDSO specification to continue.

13.	(i) Magneto telephone with Electro dynamic tranducer (ii)Desk Type Electronic Magneto Telephone	3100348	Item decontrolled. RDSO specification to continue.
14.	IP Based Integrated Passenger Information System	3100348	Being directly related to relaying information 24/7 to general public, and being face of IR, quality and service has to be ensured. RDSO specification, vendor development and inspection to continue.
15.	VHF Based Approaching Train Warning system for Track Maintenance	3100114	Item decontrolled. RDSO specification to continue.
16.	Voice Data Logger/Monitor for Control Circuits	3100172	Item decontrolled. RDSO Specifications to continue. RITES/Third Party inspection is mandated.
17.	Emergency socket Box of FRP material	3100201	Item decontrolled. RDSO specification to continue. RITES/Third party inspection is mandated.
18.	SMPS based Telecom Integrated Power Supply System for Station (TIPSS)	3100497	Item decontrolled.